



Gary R. Herbert
Governor
Major General Brian L. Tarbet
The Adjutant General

State of Utah

UTAH NATIONAL GUARD

12953 MINUTEMAN DRIVE
DRAPER, UTAH 84020-9286
(801) 432-4400

M0350042
CC: Leslie

October 12, 2010

Army Garrison Camp Williams

Mr. Todd Cusick
Construction Materials Company
71 East Wadsworth Park Drive
Draper, UT 84020

Dear Mr. Cusick,

The Utah Army National Guard would like to inform Construction Materials Company (CMC) that debris from CMC work at the Point South location flowed onto Army Garrison Camp Williams (AGCW) property (see enclosed photos) sometime during August of this year. The debris flow has caused minor damage to the adjacent AGCW channel and surrounding habitat.

While it is not clear what happened at the open pit mine to cause the erosion event, AGCW feels some erosion controls should be corrected so that the problem does not escalate. With regard to the debris that flowed onto AGCW property, the debris in the channel needs to be removed so that it does not impede surface water flow. In addition to debris removal, it has been suggested that an erosion control measure, such as a wire-gabion check dam be installed in the channel to prevent further habitat deterioration.

Can CMC provide AGCW with any of the above mentioned solutions? Our main concern is to reduce the risk of a debris flow event in the future and protect the existing habitat.

Should you have any questions or concerns, please call Sergeant Major David Hamilton at 801-878-5657. Please respond by November 17 2010 so that we can have mitigation in place before the next spring runoff.

Sincerely,

Lieutenant Colonel Michael D. Bartlett
Army Garrison Camp Williams
Training Site Manager

Enclosures

Photo 1-CMC Operations and Army Garrison Camp Williams Boundary



Photo 2-CMC Operations Surface Water Flow Direction

